



KEEP ALL COMPONENTS LEADS SHORT

ALL RESISTORS 1/8 WATT OR 1/4 WATT

FOR 20mA LASER DRIVE CURRENT
CHANGE 180 OHM TO 100 OHMS
AND 47 OHMS TO 33 OHMS.

MUST BE 74HCT14
OR 74HC14

